

Safari Landscape and Horticultural
 Solutions
 P O Box 5742
 Spring Hill, FL 34611
 352-442-5740
 SafariLandscapeandhortsvc@gmail.com

Estimate

Date	Estimate #
8/4/2017	Morris Brid

Name / Address
Cory Lakes CDD 10441 Cory Lakes Dr Tampa, FL 33647

			Project
Description	Qty	Cost	Total
A standard industry installation. Provide all material to install lighting system. All wires will be direct burried approximately 2" under ground. All wire connections will be done using a direct burried wirenut plus zip tie to prevent failure. All fixtures will be set and adjusted using manufacture's pedestals.		0.00	0.00
See Drawing.			
Lighting system - Exit side Sago (6), Bottle Brush (6), Ribbon Palm (2), Brodie Cedar (2), Ribbon Palm (3), Ligustrum (2), Ribbon Palm (1), Bottle Brush (2), Ligustrum (1), Ligustrum (1), Bottle Brush (2), Queen Palm (2)	30	377.00	11,310.00
Lighting system - Guard Shack Washingtonia (3).	3	377.00	1,131.00
Lighting system - Center Median Sylvester (8), Sylvester (2), Sylvester (2), Sylvester (2), Sylvester (2)	16	377.00	6,032.00
Lighting System - Entry Side Corner (12), Ribbon Palm (1), Ribbon Palm (2), Queen Palm (2), Ligustrum (2), Sable (1), Sable (1), Sable (1), Queen Palm (1), Queen Palm (1), Date Palm (1)	23	377.00	8,671.00
Lighting system - Inside Entry Median Queen Palms (5)	5	377.00	1,885.00
Lighting system - Inside Exit side Paurotis Palm (2), Euro Palm (1), Queen Palms (3)	6	377.00	2,262.00
		Total	

Customer Signature

Safari Landscape and Horticultural
 Services
 P O Box 5742
 Spring Hill, FL 34611
 352-442-5740
 Safarilandscapelandhortsvc@gmail.com

Estimate

Date	Estimate #
8/4/2017	Morris Brid

Name / Address
Cory Lakes CDD 10441 Cory Lakes Dr Tampa, FL 33647

Project

Description	Qty	Cost	Total
Lighting system - Inside Center Median Reclinata Palm (3), Sylvester Palm(2), Ribbon Palm (1), Sylverster Palm (2), Washingtonia Palm (6), Ribbon Palm (3), Washingtonia (6), Sylvester Palm (2), Sable Palm (3), Sable Palm (2), Sable Palm (2), Sylvester Palm (2), Sable Palm (2), Sable Palm (1), Sylverster Palm (2), Sable Palm (3), Sylvester Palm (2), Washingtonia Palm (2), Sylvester Palm (2), Washingtonia Palm (2), Sylvester Palm (1), Washingtonia Palm (2), Datel Palm (2), Sylvester Palm (2), Reclinata Palm (3)	60	377.00	22,620.00
		Total	\$53,911.00

Customer Signature _____

Safari Landscape and Horticultural
 Services
 P O Box 5742
 Spring Hill, FL 34611
 352-442-5740
 Safarilandscapelandhortsvc@gmail.com

Estimate

Date	Estimate #
8/4/2017	Cross Creek

Name / Address
Cory Lakes CDD 10441 Cory Lakes Dr Tampa, FL 33647

			Project
Description	Qty	Cost	Total
A standard industry installation. Provide all material to install lighting system. All wires will be direct buried approximately 2" under ground. All wire connections will be done using a direct buried wirenut plus zip tie to prevent failure. All fixtures will be set and adjusted using manufacture's pedestals.			
See Drawings.			
Lighting system - Entrance Guard Shack Paurotis Cluster (5), Date Palm (6), Riclanata (3)	14	377.00	5,278.00
Lighting system - Exit Side Paurotis Palms (7), Ligustrum (3)	10	377.00	3,770.00
Lighting system - Center Sylvester Palm (2)	2	377.00	754.00
Lighting system - Road Washingtonia (36)	36	377.00	13,572.00
Lighting system - Belltower Belltower (4) Lights	4	377.00	1,508.00
Lighting system - Entry Queen Palms (8), Ligustrum (2), Ligustrum (2), Queen Palms (2), Queen Palms (2), Queen Palms (12)	28	377.00	10,556.00
Lighting system - Exit	6	377.00	2,262.00
		Total	

Customer Signature

Cum gratia

Estimate

Date	Estimate #
8/4/2017	Cross Creek

Name / Address
Cory Lakes CDD 10441 Cory Lakes Dr Tampa, FL 33647

Project

Description	Qty	Cost	Total
Riclanata Palms (3), Italian Cypress (2), Riclanata Palms (1).			
		Total	\$37,700.00

Customer Signature _____

Safari Landscape and Horticultural
 P O Box 5742
 Spring Hill, FL 34611
 352-442-5740
 Safarilandscapelandhortsvc@gmail.com

Estimate

Date	Estimate #
7/21/2017	Club/Pool

Name / Address
Cory Lakes CDD 10441 Cory Lakes Dr Tampa, FL 33647

Project

Description	Qty	Cost	Total
A standard industry installation. Provide all material to install lighting system. All wires will be direct burried approximately 2" under ground. All wire connections will be done using a direct burried wirenut plus zip tie to prevent failure. All fixtures will be set and adjusted using manufacture's pedestals.			
Lighting system (Club House) Reclinata Palm(3), Ligustrum trees(2), Crape Myrtle(2), Large DatePalms(6), White Bird of Paradise(4)	17	377.00	6,409.00
Lighting system(Dock) Steps(6), Dock posts(10), Recessed steps(2)	18	377.00	6,786.00
Lighting system(Pool) Tall Majools recessed cans(6), Path lights along pool deck(30),Up light in landscape(40)	76	377.00	28,652.00
		Total	\$41,847.00

Customer Signature _____